

MIDWEST ATC SERVICE, INC.
"FLIGHT LEVELS ABOVE THE REST"
WATERBURY-OXFORD FAA CONTRACT TOWER


April 11, 2006

To: Whom it may concern,

I understand that there is some concern about the accuracy of the SAI Graphical display at the Oxford Airport. The tower personnel at Oxford have been observing the FAA AWOS and the SAI Graphical displays side by side for the past two years and can state that there have been no discrepancies observed between the two units. They are now and always have been observed displaying the same accurate information.

In addition to this, the FAA requires Oxford Tower to terminate the long-line transmission of the AWOS data and manually disseminate our METAR/SPECI observations. This mandate disables the call-in feature of the AWOS. The SAI Graphical display fills this gap in the system. The SAI Graphical display is a very useful tool to the flying community at the Oxford Airport and in my opinion needs to be returned to service as soon as possible.

Respectfully,



Garry Evans
Air Traffic Manager,
Waterbury-Oxford FCT